SPRING LAKE ESTATES HOME OWNERS ASSOCIATION



P.O. Box 5701 Rockford, IL 61125

2019 INSPECTION REPORT Permit No. 17607 Dam ID No. IL 00545

SPRING LAKE DAM WINNEBAGO, COUNTY, ILLINOIS



Observed by: Arc Design Resources, Inc. 5291 Zenith Parkway Loves Park, IL 61111

Revision Date: November 27, 2019



Table of Contents

1. Use of the Lake	3
2. Operations	3
3. Emergency Conditions	3
4. 2019 Observed Deficiencies and Recommendations	4
5. Annual and Semi-Annual Maintenance	7
6. Owner's Maintenance Statement	12
Γables and Figures	
Site photos	13
IDNR Inspection Forms	16
Plat Maps from Previous Reports	33

Use of the Lake

Spring Lake is used for recreational purposes. Small sailboats, canoes, rowboats, or kayaks are used on the lake by the residents of Spring Lake Estates. Electric trolling motors are allowed, gas powered engines are not.

Operations

The lake serves two functions. One is for the recreational and aesthetic value described above. The other is to provide storm water management for the subdivision development. The lake level is controlled by a square concrete spillway with a 60" diameter pipe outfall to Spring Creek. The normal water level is estimated to be 839.56 based on WinGIS data. The high-water elevation is calculated to be 843.55. the top of the dam is approximately 844.5. Storm water will flow into the principle spillway once it reaches an elevation higher than 839.56 and will flow into the emergency spillway at elevation 843.55. At the high-water level, the dam stores approximately 36 acre-feet of water.

Once water begins to flow over the emergency spillway, access to the houses on the south end of Montlake Drive will be impaired and potentially dangerous. During extreme flood events, first responders will be directed to contact homeowners in this area for assistance.

Emergency Conditions

Emergency Conditions (some of this material is taken from Hanson's 2018 report) - If a condition arises where there is a possibility of dam failure, then the following procedures will be followed:

- 1. The lake level can be lowered by opening the dewatering valve (providing the valve is operational, and access can be safely achieved). This valve should only be opened if there is a possibility of dam failure when the lake is not in a flood condition. During extreme flooding conditions, it is not safe to access the dewatering valve. During extreme flooding, the dewatering valve does not significantly increase discharge from Spring Lake so it is not imperative the valve be opened.
- 2. Provisions will be made to obtain equipment in a ready condition in case it is necessary to breach the dam in a controlled manner. The breach locations shall be determined considering operator safety and the level of downstream safety. The primary location for the breach shall be the easternmost end of the. A breach at the east end will keep excess flood waters in the existing

creek channel and limit damage to the existing dam outfall structures and systems.

- 3. The lake, the primary spillway, and the dam will be monitored for changes in conditions.
- 4. The following agencies will be notified by the Spring Lake Estates Home Association of the condition of the Spring Lake Dam.
- (1) Emergency 911 for the City of Rockford
- (2) Illinois Department of Natural Resources Dam Safety Engineer, Telephone Number (217) 782-4427.
- (3) Illinois Emergency Management Agency
 Telephone Number (800) 782-7860 (only from within Illinois)
- (4) Winnebago County Emergency Services Disaster Agency Civil Defense
 Telephone No. (815) 966-2900
- (5) Rockford Police Telephone Number (815) 966-2900
- (6) Rockford Public Works Department Telephone Number (779) 348-7300 After Hours (779) 348-7260
 - 5. These agencies should alert the public concerning the status of the dam and advise as to appropriate actions to take to prevent the loss of life and property damage. However, such notification and advice will in no way relieve the Spring Lake Estates Home Association from liability in case of dam failure. The Spring Lake Home Association should keep their insurance policy for the dam and the associated impoundment in force.
 - 6. If possible, any item, including debris, which is interfering with the normal flow over the primary and emergency spillways, will be removed.
 - 7. A subsequent re-inspection of the dam will be performed by a Professional Engineer to determine possible causes of failure and possible corrective actions to take.

2019 Observed Deficiencies and Recommendations

Dam inspection observations revealed several items needing repair or maintenance. The items listed in the following repair inventory fall into the category defined in the dam inspection Condition Codes as minor maintenance needed within the next year (MM) or

immediate maintenance to restore the dam to its original intended safety or integrity (IM). Items like long term vegetation restoration fall into the category requiring ongoing observations to make sure that the intended goal of the turf restoration is achieved.

Recommendations on sloughing repairs and minor holes are listed in the inventory. Placement of compacted clay soil means compacting the soil to 95% of the soil's maximum density. To achieve this density, the soil must be placed in lifts or layers not exceeding 8" in total thickness. Once each layer is correctly compacted, the next layer of soil may be added and compacted. This systems of placing, compacting, and adding the additional soil shall be repeated until the desired depth of fill placement is reached. Compacted clay soil should be placed until the depth of hte clay is within 4" of the existing dam surface. The final four inches are reserved for the placement of topsoil.

Seeding of all repaired areas shall follow the specifications listed herein. Optimal times for seeding occur in the first two weeks of May or the first two weeks of September.

Reconstruction of the rip rap shoreline protection must follow the detail included in this report. The shoreline protection repairs should take place at locations where sloughing or holes in the dam are repaired. Each section of shoreline protection repair should be at least 6 feet long for each section repaired. The goal of this approach is to repair the shoreline protection along the entire length of the dam over the term of the next ten years of dam repairs.

ate:

26-Nov-19



Onning Lake Bass Bassis Investors		
Spring Lake Dam Repair Inventory Repair items noted from dam inspection on October 31, 2019		
This inventory accompanies the dam site plan showing WinGIS property lines, ground contours, an underlying aerial photo and notations of various items requiring maintenance or repair. This inventory is meant to assist property owners in determining what items are located on their property that are in need of maintenance.		
Item Description on Dam Site Plan	Detailed Description	Repair Recommendation
Minor sloughing along bank	Soil embankment slope has become steeper due to lack of stabilizing rip-rap	When lake level is down 2 feet, recompact weakened soil plane, add compacted clay, line with geotextile fabric, pull up sloughed rip rap along repaired slope to two feet above normal water level.
Hole 1	6" diameter hole in surface of dam face	Remove vegetation, fill with compacted clay, cap with 4" of topsoil, seed with specified seed mix.
Hole 2	6" diameter hole in surface of dam face at water level	Remove vegetation, fill with compacted clay, cap with 4" of topsoil, seed with specified seed mix.
Hole 3	3-4" diameter hole in surface of dam face	Remove vegetation, fill with compacted clay, cap with 4" of topsoil, seed with specified seed mix.
7 small trees in this area, four on the back slope of the dam must be removed	3 of the 7 trees in this area must be removed because they are on the back slope of the dam. The remaining trees are in the creek channel.	Remove tree, cut stump off level with ground surface, treat stump with herbicide.
Hole 4	3-4" diameter hole in surface of dam face, back slope	Remove vegetation, fill with compacted clay, cap with 4" of topsoil, seed with specified seed mix.
Hole 5	3-4" diameter hole in surface of dam face	Remove vegetation, fill with compacted clay, cap with 4" of topsoil, seed with specified seed mix.
Hole 6	3-4" diameter hole in surface of dam face	Remove vegetation, fill with compacted clay, cap with 4" of topsoil, seed with specified seed mix.
Hole 7	4' x 3' slough in surface of dam face upslope from rip- rap	Remove dislodged soil and vegetation, fill with compacted clay, cap with 4" of topsoil, seed with specified seed mix.
Hole 7a - related to adjacent slough	2' x 2' slough in surface of dam face upslope from rip- rap	Remove dislodged soil and vegetation, fill with compacted clay, cap with 4" of topsoil, seed with specified seed mix.
Hole 8	minor slough in surface of dam face	Removed dislodged soil, remove vegetation, fill with compacted clay, cap with 4" of topsoil, seed with specified seed mix.
Vegetation along the back slope of the embankment must be removed	Evergreen plants on both sides of elevated walkway to dam	Remove plant material and roots. Replace disturbed soil with compacted clay, cover with 4" of topsoil, apply specified seed mix.
Hole 9, animal bore	2" diameter hole in surface of dam face	Remove vegetation, fill with compacted clay, cap with 4" of topsoil, seed with specified seed mix.
Hole 10	3-4" diameter hole in back slope surface of dam face	Remove vegetation, fill with compacted clay, cap with 4" of topsoil, seed with specified seed mix.
Vegetation along both sides of the dam embankment must be modified	Excessive plant growth on dam embankment is not acceptable.	Remove woody plant material and roots. Replace disturbed soil with compacted clay, cover with 4" of topsoil, apply specified seed mix.
Principle spillway with newly fabricated metal grate.	Principle spillway, top grate, 60" dia pipe outfall.	Lake drawdown valve must be modified to be operational from top of new metal grate. A manually operated gate valve is recommend with an extended valve shaft and operating wheel.
Emergency spillway location from observation.	The emergency spillway appears to be set at the appropriate grade and will function as originally designed. WinGIS does not show the overland flood route easements as shown on the original construction plans.	Consider replatting a portion of the property to correctly show the overland flood route in a properly sized drainage easement. Priority is low.

Turf restoration will require more arduous efforts. Tree removal in the zone of the dam embankment, as shown on the exhibits is required. The 4" diameter tree and larger must have the stumps removed and backfilled with compacted clay and topped with 4"

of locally sourced topsoil. Trees smaller than 4" diameter should be cut level with the existing grade and treated with a herbicide. Trees and branches must also be removed from the slopes. Once cleared of trees and woody shrubs, the remaining vegetation must be mowed with a brush hog or large rotary mower. Overgrowth should be removed from the slopes to reduce the presence of existing seeds. Optimal times of the year to complete this work are before or after the growing seasons. Once the overgrowth is removed, the dam embankments are to be seeded with the seed mix as specified below.

IDOT Class 2 Roadside Mix

Application Rate: 200 lbs./acre

Pure Seed	Description	Germination	Source Origin
49.33%	Inferno Tall Fescue	98%	OR
24.29%	Perennial Ryegrass*	96%	OR
19.59%	Creeping Red Fescue*	88%	CAN
4.87%	Red Top	85%	IL

0.00% Other Crop Date Tested 1/19 0.05% Weed Seed IL. Permit 2411

1.87% Inert Matter Net Weight 50 lb. / 22.68 kg.

Noxious Weeds: NONE Sell By 1/20

*Variety Not Stated Source: Martenson Turf Products, Inc.

250 W. Adams P.O. Box 218

Waterman, IL 60556-0218 Phone: 800-833-2290 Fax: 815-264-3324

Website: www.mtp78.com

This process may take one or more growing seasons to provide a homogeneous turf coverage on the earth embankment. The resultant turf coverage can be mowed twice per year. The grass will be visually acceptable long or mowed.

Other required maintenance items are defined in the inventory.


Annual and Semi-Annual Maintenance


A regular maintenance program is recommended and should include the following:

- 1. The dewatering valve will be exercised three times per year (Spring, Summer, and Fall), to ensure that it is operable. Moving parts will be lubricated in the Spring and Fall.
- 2. The slope of the upstream and downstream dam face will be kept clear of brush and tree growth. The slope will be maintained in a grass condition with a mowed height of 6 inches or less.

3. Semi-annual inspections will be made for animal habitations in the dam face. Animal habitations that are found will be destroyed, filled with compacted earth, and seeded.

Additional information on dam safety, maintenance and modes of dam failure can be found on the Illinois Department of Natural Resources Dam Safety website. https://damsafety.org > illinois





SUMMARY OF MAINTENANCE DONE AND/OR REPAIRS MADE SINCE THE LAST INSPECTION

DATE OF PRESENT INSPECTION	November 27, 2019
DATE OF LAST INSPECTION	November 28, 2016
1. <u>EARTH EMBANKMENT DAMS</u>	
2. CONCRETE MASONRY DAMS	
3. PRINCIPAL SPILLWAY New grate on top of structure	
4. OUTLET WORKS Grate on outlet pipe repaired	
5. <u>EMERGENCY SPILLWAY</u>	

Owner's Maintenance Statement

Dam Identification Number 00545. in Winebugo County,	dam,
Dam Identification Number 00545 . in Winebus County,	
am maintaining the dam in accordance with the accepted maintenance plan which is part of	
Permit Number 17607.	
Signature	_
12/20/19 Date	_
- / Date	
Owner's Operation and Maintenance Plan Statement	
1. Josh Spencer President, SLEHA owner of Spring Lake	dam,
Dam Identification Number 00545 , in County,	
have reviewed the operation and maintenance plan including the Emergency Action Plan (EAP),	
which is part of, Permit Number 17 607	
I have enclosed the appropriate revisions or	
have determined that no revisions to the plan are necessary. Signature	
12/20/19 Date	

The Department of Natural Resources is requesting information that is necessary to accomplish the statutory purpose as outlined under the River, Lakes and Streems Act, 615 ILCS 5. Submitted of this information is REQUERED. Feature to provide the required information could result in the initiation of non-compliance procedures as outlined in Section 5792.160 of the "Rules for Construction and Maintenance of Denre".



Principal spillway – new trash rack



Inside the drop inlet, draw down



East end of dam, shoreline sloughing



East end, dam back slope, tree coverage.



Sloughing on dam face, multiple locations. Mostly good turf coverage.







Poor dam vegetation coverage



Shoreline vegetation to be removed.



Planters and stump removal required.



Excessive vegetation to be removed.





Outfall pipe grate.



Newly planted oak trees, remove the three trees on the dam.



Hole 1 - repair



Emergency spillway over an access road.



Hole 2 - repair

Dam Inspection Report

Name of [Dam		Spring Lake Dam		Dam ID No.	l	L 00545	
Permit Nu	ımber	17	607		Class of Da	am <u>II</u>		
Location	NE 1/4	Section	9	Township	44N	Range	2E- 3rd F	Principal Meridian
Owner _	Spring	Lake Estate Name	es Home O	wners Assn.	_	(815) 218-16	662 phone Nun	obor (Day)
		IName				1 616	priorie ivuri	ilbei (Day)
		P.O. Box Stree			_	Tolor	phone Num	ber (Night)
Rock Cit		-	61125 Zip Code	County				isci (riigili)
Type of D	am				Eart	hen fill		
Type of S	pillway				Concrete b	oox drop inlet		
Date(s) In	spected					Oct-19		
Weather \	When Ins					tly Cloudy, Calm		
Temperat	ure Whe	n Inspecte	ed			48°		
Pool Eleva						Normal Pool 83	39.56	
Tailwater				Normal 830 +-				
				Inspection	Personnel:			
				•		Е		Droinet Manager
					Altenhoff, P Name	· C ·	Title	Project Manager
				<u> </u>	Name		Title	
Profession	nal Engir	neer's Sea	I		Name		Title	

The Department of Natural Resources is requesting information that is necessary to accomplish the statutory purpose as outlined under the River, Lakes and Streams Act, 615 ILCS 5. Submittal of this information is REQUIRED. Failure to provide the required information could result in the initiation of non-compliance procedures as outlined in Section 3702.160 of the "Rules for Construction and Maintenance of Dams".

CONDITION CODES

- NE No evidence of a problem
- GC Good condition
- MM Item needing minor maintenance and/or repairs within the year, the safety or integrity of the item is not yet imperiled
- Item needing immediate maintenance to restore or ensure its safety or integrity
- EC Emergency condition which if not immediately repaired or other appropriate measures taken could lead to failure of the dam
- OB Condition requires regular observation to ensure that the condition does not become worse
- NA Not applicable to this dam
- NI Not inspected list the reason for non-inspection under deficiencies

EARTH EMBANKMENT

	CONDITION		RECOMMENDED REMEDIAL MEASURES
ITEM	CODE	DEFICIENCIES	AND IMPLEMENTATION SCHEDULE
Surface Cracks	NE, GC		
Vertical and Horizontal Alignment of Crest	NE, GC		
Unusual Movement or Cracking At or Beyond Toe	NE		
Sloughing or Erosion of Embankment and Abutment Slopes	ММ	Several locations of minor sloughing, animal bores or other small diameter holes	fill holes, repair sloughing, restore shoreline rip rap bank protection to provide the required minimum bank stabilization. Refer to dam site plan for specific locations
Upstream Face Slope Protection	MM, IM, OB	excessive vegetative cover must be removed. Detailed observations not possible with existing coverage	Remove woody and tall weeds. Reestablish turf using a specified seed mix as detailed in this report. Observe for the next two growing seasons for achievement of intended goal of uniform earthen embankment turf protection along entire 1,300 feet of dam.
Seepage	NE, GC		
Filter and Filter Drains	N/A		No drains or drain outfalls observed.

EARTH EMBANKMENT

(Continued)

-	CONDITION		RECOMMENDED REMEDIAL MEASURES
ITEM	CODE	DEFICIENCIES	AND IMPLEMENTATION SCHEDULE
Animal Damage	ММ	One animal bore hole observed, see dam site plan	fill hole, reseed
Embankment Drainage Ditches	NE		
Vegetative Cover	MM, IM, OB	Significant variability of vegetative cover is a problem for the earthen dam. Tree and woody vegetation exists on the	Brush hog areas of dam where vegetation is greater than 3" in height. Remove trees, remove planted landscape beds, remove woody shrubs. Apply herbicide to tree stumps. Apply seed and fertilizer to establish a uniform turf ground cover for the entire dam length. Observe semi-annually until goal is achieved.
Shoreline wave and water level protection	ММ	Rip rap shoreline protection has sloughed in many areas along the shoreline. Lack of the rip rap shoreline protection is a leading cause of minor sloughing.	Incrementally attack this problem when the lake levels can be dropped by at least 2 feet. Either by machine or hand method, pull up the sloughed rip rap back into place along the shore after the shore has been regraded and protected with geotextile fabric to accept the relocated rip rap shoreline protection.
Other			
Other			
Other			

CONCRETE OR MASONRY DAMS

ITEM	CONDITION CODE	DEFICIENCIES	RECOMMENDED REMEDIAL MEASURES AND IMPLEMENTATION SCHEDULE
Seepage	N/A		
Structure to Abutment/ Embankment Junctions	N/A		
Water Passages	N/A		
Foundation	N/A		
Surface Cracks in Concrete Surfaces	N/A		
Structural Cracking	N/A		
Vertical and Horizontal Alignment	N/A		

CONCRETE OR MASONRY DAMS (CONTINUED)

	T = =		
	CONDITION		RECOMMENDED REMEDIAL MEASURES
ITEM	CODE	DEFICIENCIES	AND IMPLEMENTATION SCHEDULE
Monolith Joints	N/A		
Construction Joints	N/A		
Spalling of Concrete	N/A		
3			
Filters, Drains, etc.	N/A		
Riprap	N/A		
Other (Name)	N/A		
•			
	1		

IF THE DAM IS GATED - Fill out the portion of the Principal Spillway Form related to Gated Spillways

PRINCIPAL SPILLWAY APPROACH CHANNEL

	CONDITION		RECOMMENDED REMEDIAL MEASURES
ITEM	CODE	DEFICIENCIES	AND IMPLEMENTATION SCHEDULE
Debris	N/A		
Side Slope Stability	N/A		
Side Slope Stability	IN/A		
Slope Protection	N/A		
Slope Protection	IN/A		
Other (Name)			
Other (Name)			
Other			
Other			
Other			
Other			
Other			
Other			

X Drop Inlet Spillway			Ilway Structure Gated	
ITEM	CONDITION CODE	DEFICIENCIES	RECOMMENDED REMEDIAL MEASURES AND IMPLEMENTATION SCHEDULE	
Erosion, Spalling, Cavitation	NE, GC			
Structure to Embankment Junction	NE, GC			
Drains	N/A			
Seepage Around or Into Structure	NE, GC			
Surface Cracks	NE, GC			
Structural Cracks	NE, GC			

IF THE SPILLWAY IS GATED FILL OUT THE GATES SECTION

PRINCIPAL SPILLWAY
(Continued)

X Drop Inlet Spillway		Overflow Spi	illway Structure Gated
ITEM	CONDITION CODE	DEFICIENCIES	RECOMMENDED REMEDIAL MEASURES AND IMPLEMENTATION SCHEDULE
Alignment of Abutment Walls	N/A		Drop structure appears to be a single poured vertical concrete box in good condition.
Construction Joints	GC		Concrete pipe outfall was observed its full length. Pipe joints all appeared in good condition.
Filter and Filter Drains	N/A		
Trash Racks	GC		Newly constructed rack is in good condition.
Bridge and Piers	N/A		
Differential Settlement	GC		At normal pool elevation, water flows over the drop inlet on the west side of the vertical drop box. The box is not perfectly level but it is close. Currently this in not an issue.
Other (Name)			

IF THE SPILLWAY IS GATED FILL OUT THE GATES SECTION

(Continued)

X Conduit		(Continued)	Gated
ITEM	CONDITION CODE	DEFICIENCIES	RECOMMENDED REMEDIAL MEASURES AND IMPLEMENTATION SCHEDULE
Erosion, Spalling, Cavitation	NE, GC		
Joint Separation	NE, GC		
Seepage Around of/ Into Conduit	NE, GC		
Surface Cracks	NE, GC		
Structural Cracks	NE, GC		
Trash Racks	NE, GC	Downstream end of conduit is fitted with a metal grate.	Secure the metal grate to the outlet headwall with at least five 1/2" diameter wedge anchors on the top and both sides of the grate.
Differential Settlement	NE, GC		
Alignment	NE, GC		
Other (Name)			

IF THE SPILLWAY IS GATED FILL OUT THE GATES SECTION

(Continued)

	CONDITION		DECOMMENDED DEMEDIAL METACHDES
ITEM	CONDITION CODE		RECOMMENDED REMEDIAL MEASURES
HEM	CODE	DEFICIENCIES	AND IMPLEMENTATION SCHEDULE
Erosion, Spalling, Cavitation	N/A		
Erosion, opaning, cavitation	IN/A		
Structure to Embankment	N/A		
Junction			
Construction Joints	N/A		
Construction Joints	IN/A		
Expansion and Contraction	N/A		
Joints			
-			
Differential Settlement	N/A		
Surface Cracks	N/A		
-			
Structural Cracks	N/A		
Wall Alignment			
wall Alignment			
Other (Name)			

IF THE SPILLWAY IS GATED FILL OUT THE GATES SECTION

Chute

X Principal Spillway) Dewatering		Other:
ITEM	CONDITION CODE	DEFICIENCIES	RECOMMENDED RE AND IMPLEMENTAT	EMEDIAL MEASURES ION SCHEDULE
Gate Sill	GC			
Gate Seals	GC			
Gate and Frame	ММ	The drawdown valve needs to be replaced due to age and inoperability from the top of the structure.		a gate valve and provide a long valve stem with sufficient llow for operation from the top of the trash rack.
Operating Machinery	ММ		Gate cannot be operate the gate difficult and so	ed from the top of the structure making maintenance of mewhat dangerous.
Emergency Operating Machinery	N/A			
Other (Name)				
Other				

<u>OUTLET WORKS</u> IF SEPARATE FROM PRINCIPAL SPILLWAY STRUCTURE

ITEM	CONDITION CODE	DEFICIENCIES	RECOMMENDED REMEDIAL MEASURES AND IMPLEMENTATION SCHEDULE
Erosion, Spalling, Cavitation	N/A	52.70.2.70.20	
Joint Separation	N/A		
Seepage Around or Into Conduit	N/A		
Intake Structure	N/A		
Outlet Structure	N/A		
Outlet Channel	NE, GC		Water from the principle spillway discharges through the 60" RCP directly into Spring Creek. The headwall and channel leading to the main creek channel is short, less than 10 feet and in good condition.
Riprap			
Other (Name)			
Other			

ENERGY DISSIPATOR
Outlet Wor

X Princip Type:	al Spillway	Conduit	Outlet Works
ITEM	CONDITION CODE	DEFICIENCIES	RECOMMENDED REMEDIAL MEASURES AND IMPLEMENTATION SCHEDULE
Erosion, Spalling, Cavitation	N/A		
Structure to Embankment Junction	N/A		
Construction Joints	N/A		
Surface Cracks	N/A		
Structural Cracks	N/A		
Differential Alignment	N/A		
Expansion and Contraction Joints	N/A		

ENERGY DISSIPATOR

(Continued)

X Pri	ncipal Spillway	(==:::::===,	Outlet Works
ITEM	CONDITION CODE	DEFICIENCIES	RECOMMENDED REMEDIAL MEASURES AND IMPLEMENTATION SCHEDULE
Riprap	GC		
Outlet Channel	GC		
Debris	NE		
Other (Name)			
Other			
Other			
Other			

EMERGENCY SPILLWAY

Earth			Other: Name	Earthen with paved roadway
ITEM	CONDITION CODE	DEFICIENCIES	RECOMMENDED REMEDIAL MEAS AND IMPLEMENTATION SCHEDUL	
Erosion	NE			
Weeds, Logs, Other Obstructions	NE			
Side Slope Sloughing	NE, GC			
Vegetation	GC			
Sedimentation	N/A			
Riprap	GC			
Settlement of Crest	NE			
Downstream Channel	GC		Spillway route includes flowing over a obstructions and is in good condition.	private drive. The roadway is clear of
Other (Name)				

DOWNSTREAM DEVELOPMENT APPROXIMATE WIDTH OF AFFECTED FLOODPLAIN

MIL	E5

MILES DOWNSTREAM FROM DAM				DO	WNS	STRE	EAM DEVELOPMENT							oss o Life oten			Los oten	s	SKETCH IN DEVELOPMENTS DOWNSTREAM OF THE DAM
	OCCUPIED HOMES	UNOCCUPIED HOMES	AGRICULTURAL BUILDINGS	INDUSTRIAL BUILDINGS	COMMERCIAL BUILDINGS	SCHOOLS	HOSPITALS	ROADS & BRIDGES	DAMS	OVERHEAD UTILITIES	OTHER DEVELOPMENT (Name	OTHER DEVELOPMENT (Name	NONE	1 TO 10	OVER 10	MINIMAL EXPECTED	APPRECIABLE EXPECTED	EXCESSIVE EXPECTED	RESERVOIR
0 to 1/4	See	exh	ibit a	ttach	ned b	elov	V.						Х			Х			
1/4 to 1/2													Х			Х			/] /
1/2 to 3/4													Х			Х			(/
3/4 to 1													Х			Х			
1 to 1-1/4													Х			Х			
1-1/4 to 1-1/2													Х			Х			
1-1/2 to 1-3/4													Х			Х			/ \
1-3/4 to 2													Х			Х			/ (
OVER 2													Х			Х			Downstream
																			Floodplain '

The number of homes, buildings, or other items in the floodplain downstream of the dam should be placed in the appropriate row and column to designate their location.



The partial map from WinGIS shows the dam location and the downstream conditions which extend approximately 1 mile down stream to Alpine Road and Spring Creek. Residential development is located downstream but is situated outside of the floodway and floodplain. Data taken from 2016 FEMA information.

NOTES TO USERS

The time is to see to expense to the control force an extend fragment of the control force and the control for

The recognity Try (2004) and the Control of the Con

Considerate Manufactures over a factory may be proved with best former over 1976, and a 429 object 201, does not see the factory manufactures best best for an appropriate of considerate former best former part the "Part Mexicans May considerate and accommodate former best former," a Shaper Christian and the considerate days of the Section, a dispersion of the considerate part to the considerate of the considerate and the considerate considerate of the considerate of the considerate of the considerate part to the considerate of the considerate of the considerate considerate of the considerate of the considerate of the considerate considerate of the considerate of the considerate of the considerate considerate of the considerate of the considerate of the considerate considerate of the considerate considerate

Sections 2 to Papagage over consiste at the control of consiste control of the Section was based on special communities at the special or representative or the Section State or color Majora. Provide color on the control tradege and or colored or the Department of the control of the colored tradege.

control was faller forced from Proper Force Property to control by Read control property of the Control of Time Property Street of the final appropriate faller short to Malaches are found induced the control than the Control of the

he measure that a first property of the state and first that the second state of the s

Telephoneti I and The Section of the

The special property of the second states of the se

Charles chartes about to the 100 per synch too delay

For the states, the contract of the states and the states of the states

Compare facts there is the man professor of the term and purpose the term of pulsarian fractions. Design the state of advances to the compared term only facts according to the man pulsarian man are stated to the state of the s


The control of the co

or peach and the book property of the 1999. Another school as a peach and the peach and the 1999 and the school as and the peach and to property of the peach and the transmission of the peach and th

Print Print Print to good years of her state has the

he pulle has been proved to but no merced for figure in the land of the figure in the

PANEL INDEX









27

NOTES TO USERS

The first think of the second of the second first first the second of th

Consoli Base Mand Educations over a directly upon and terrelated in the hard memory. Jestima Education is also forward that for the Tellitration memory between the consolidation and the product of t

Constant of the freedomy are uniqued to one contain to respect to the contain the transfer of the forest area being a square planetime at the transfer of represents of the following of the results of the contain the property of the contain the contain and the following of the contains the contain the contains and a monthly of the following on the contains the contains the contains the contains and the contains and the contains the contains the contains a few following contains a property of the contains to the contains the contains and the contains the contains the contains the contains the contains and the contains the contains the contains the contains the contains and the contains the contains the contains the contains the contains and the contains the con

Congressed, hit is beginn their hearth from the to committe the Book assemble bearing from the book of the from the book to be been assemble before the book of th

"Transpolent that it has completed in the only AM. Now, or has been seen and or Political Politic to becomes delice associated to be a political politic to the fields (the only for publisher or Politic to learned appropriate betty course. If only publisher is published to produce the course of the published published to the published betty course. If only the published to th

Final sections of two days or presents to the first femous theory, because of their final final property (a). We changed to detection or goods descently opening to be seen unfield their two detections applied appears of tradeology to their sections of the one to 1.5% Applicate only property of their old the distinction for the section of their control of their old the distinction for the section of the section of their old their old to the control of flowers which the first count of motivation of their old to detect the flowers which the first count of motivation of their old to detect the flowers.

Sand Milesone Systemides Sand Service Thomas William Silver Spirits State Commitsion Spirits State State State Spirits State State

to the west access another with critical decision. It best made to the court of the court have been applied as a court to the court of the court have been applied as a court of the court

Statement and the National Statement and Sta

2-14 models the amount to get the terror before the first terror before the terror b

Companied themse (No. 10, No. 10, No.

Place lett of the basis of the first basis of the f

Course to \$5000 time forces from a \$1.00 time or execution of the course of the course

Tree Statement Program or proper prints and negotiation, many orthogonal

The professions with the form of the control of the


PANEL INDEX











PLAT NO. ONE OF

SPRING LAKE ESTATES

BEING A SUBDIVISION OF PART OF THE S. 1/2 OF THE SECTION 9, T. 44 N., R. 2 E. OF THE 3RD P. M.

WINNEBAGO COUNTY, ILLINOIS

SCALE : 1" = 100"

